

[Radiation Hardened Microcircuits]

Abstract of Disclosure

A method of radiation hardening microcircuits including the steps of removing hydrogen from the microcircuit in a vacuum furnace and annealing in deuterium-containing forming gas.

1. A method of radiation hardening microcircuits including the steps of removing hydrogen from the microcircuit in a vacuum furnace and annealing in deuterium-containing forming gas.

Figures

Figure 1: A diagram illustrating the relationship between the variables x and y . The diagram shows a set of points in a 2D space, with a line of best fit drawn through them. The axes are labeled x and y . The points are scattered around the line, indicating a positive correlation. The line is labeled with the equation $y = 2x + 1$.